





Tips & tricks

Construction work brings lots of dust every day. If this comes along with humidity, the lead feed mechanism may turn out tight or even gets blocked. But you can solve this problem in just a few steps. Good to know that Pica-Dry is now available with significant better dust- and moisture protection.





Step 1: Press out the stuck lead with a long pin from the front end. At the same time open the mechanism by pushing the transparent lead feed pipe.



Step 3: Blow air through the lead pipe from both sides, if available use compressed air.



Step 2: If step 1 did not work, try to press out the stuck lead with a long pin from the back end which may take quite high force.



Step 4: Now your Pica-Dry can be refilled with a new lead and is again ready for work.